




GY – THROUGH CABLE TO SIDE OF GROUND ROD

Pro tip: The GY connection allows you to make a connection and then finish driving the ground rod.

Ground Rod Size	Cable Size	Mold	Welding Material (Qty) P/N	Cadweld Plus Welding Material P/N
5/8" Copper-bonded Sectional (threaded) or Plain	2 SOL	GYR161T	90	90PLUSF20
	2	GYR161V	90	90PLUSF20
	1/0	GYR162C	115	115PLUSF20
	2/0	GYR162G	115	115PLUSF20
	3/0	GYR162L	150	150PLUSF20
	4/0	GYR162Q	150	150PLUSF20
	250	GYR162V	150	150PLUSF20
	350	GYR163D	250	250PLUSF20
	500	GYF163Q	400	400PLUSF20
3/4" Copper-bonded Sectional (threaded) or Plain	2 SOL	GYR181T	90	90PLUSF20
	2	GYR181V	90	90PLUSF20
	1/0	GYR182C	115	115PLUSF20
	2/0	GYR182G	115	115PLUSF20
	3/0	GYR182L	150	150PLUSF20
	4/0	GYR182Q	150	150PLUSF20
	250	GYR182V	200	200PLUSF20
	350	GYR283D	300	300PLUSF20
	500	GYF183Q	500	500PLUSF20